



WHITE



BLACK



K: 50%



M: 100% Y: 100%

CAUTION: Turn off power before use.

1. Strip stranded wires 9 mm (0.35").
2. Pretwisting unnecessary.
Hold stripped wires together with ends even
(lead stranded wires slightly).
3. Align any frayed strands or conductors.
4. Screw on connector—push wires firmly into
connector when starting.
5. To be sold only with installation instructions.

LISTED FOR USE WITH
COPPER TO COPPER

Insulation operating temperature:
105°C (221°F) Max.

623-001



Twist-on Wire Connectors

Quantity: 100



22-18 AWG; 300V Max.

Listed as splicing wire connectors
on the following stranded wire combinations:
Voltage: 300V Max.

2 or 3 #18
2, 3, or 4 #20
3, 4, or 5 #22
1 #22 w/ 1 #20 w/ 1 #18
1 #20 w/ 2 #18
1 or 2 #22 w/ 2 #18
1 to 3 #20 w/ 1 #18
1 to 4 #22 w/ 1 #18
1 or 2 #22 w/ 3 #20
1 to 3 #22 w/ 2 #20
1 to 4 #22 w/ 1 #20



Made in China



51 mm

165 mm